

FIGURE 1




FIGURE 2A




FIGURE 2B







FIGURE 2C



LOWER
404



EXTENSION FRAME
402

BRACKETS
403

CORE
UPS
FRAME
401




FIGURE 4A

FIGURE 4B




FIGURE 5B

FIGURE 5A











Figure 6












FIGURE 11

Attorney Docket No.: A2000-700219



UPS
 SYSTEM
 1201







FIGURE 13A

FIGURE 13B




FRONT VIEW 1302C

FIGURE 13C







REAR VIEW 1302D


FIGURE 13D



BEST AVAILABLE COPY



BEST AVAILABLE COPY






FIGURE 18B





FIGURE 18A






FIGURE 20





Figure 21

BEST AVAILABLE COPY



BEST AVAILABLE COPY